

**EAST - [lined duct:2]**

File View Edit Tools Window Help

Active

- L1: (0) ("tailor\$near2w
- L2: (0) ("tailor\$withwe
- L3: (12) tailor near2 w
- L4: (16) tailor near2 w
- L5: (64) tailor\$ near2
- L6: (1) engineer\$ near2
- L7: (229) tailor\$ near2
- L8: (13) 17 and surface
- L9: (8) 17 and side wit
- L10: (34) tailor\$ near2
- L11: (1) engineer\$ near
- L12: (107) tailor\$ near
- L13: (0) 112 and surfac
- L14: (0) 112 and side w
- L15: (339) (296/191).CC
- L16: (177) (296/146.5).
- L17: (662) (296/29).CCL
- L18: (0) ("117andblank"
- L19: (19) 117 and blank
- L20: (6) 117 and tailor
- L21: (0) 117 and engine
- L22: (0) 117 and engine
- L23: (11) 117 and engin

Search: List Browse Queue Clear

DBs: US-PGPUB:USPAT

Default operator: OR

Plurals

Highlight all hit terms initially

117 and engineer\$

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

- Pending
- Active
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCLS
  - (296/136.01-136.13).CCLS
- Saved
- Favorites
- Tagged (5)
- UDC
- Queue
- Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	0	("tailor\$near2weld\$near2blank").PN.	US-P GPUB	2004/12/2 7 05:57		
2	IS&R	L2	0	("tailor\$withweld\$withblank").PN.	US-P GPUB	2004/12/2 7 05:56		
3	BRS	L3	12	tailor near2 weld\$ near2 blank\$	USPA T	2004/12/2 7 05:57		
4	BRS	L4	16	tailor near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:01		
5	BRS	L5	64	tailor\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:11		
6	BRS	L6	1	engineer\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:14		
7	BRS	L7	229	tailor\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:15		
8	BRS	L8	13	17 and surface with align\$	US-P GPUB	2004/12/2 7 06:09		
9	BRS	L9	8	17 and side with flush	US-P GPUB	2004/12/2 7 06:10		
10	BRS	L10	34	tailor\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:11		
11	BRS	L11	1	engineer\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:14		
12	BRS	L12	107	tailor\$ near2 blank\$	DERW ENT	2004/12/2 7 06:15		
13	BRS	L13	0	112 and surface with	DERW	2004/12/2		

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Search List Browse Queue Clear

DBs US-PGPUB:USPAT

Default operator: OR

Plurals

Highlight all hit terms initially

sinusoidal with edge with weld\$

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

Pending

Active

Failed

"138"/\$.ccls. and line\$

(296/107.19-107.20).CCLS

(296/136.01-136.13).CCLS

Saved

Favorites

Tagged (5)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
14	BRS	L14	0	112 and side with flush	DERW ENT	2004/12/2 7 06:16		
15	IS&R	L15	339	(296/191).CCLS.	US-P GPUB	2004/12/2 7 06:33		
16	IS&R	L16	177	(296/146.5).CCLS.	US-P GPUB	2004/12/2 7 06:17		
17	IS&R	L17	662	(296/29).CCLS.	US-P GPUB	2004/12/2 7 06:33		
18	IS&R	L18	0	("117andblank").PN.	US-P GPUB	2004/12/2 7 06:33		
19	BRS	L19	19	117 and blank	US-P GPUB	2004/12/2 7 06:35		
20	BRS	L20	6	117 and tailor\$	US-P GPUB	2004/12/2 7 06:35		
21	BRS	L21	0	117 and engineered with welded	US-P GPUB	2004/12/2 7 06:35		
22	BRS	L22	0	117 and engineered	US-P GPUB	2004/12/2 7 06:35		
23	BRS	L23	11	117 and engineer\$	US-P GPUB	2004/12/2 7 06:37		
24	BRS	L24	89	wave with edge with weld\$	US-P GPUB	2004/12/2 7 06:38		
25	BRS	L25	11	sinusoidal with edge with weld\$	US-P GPUB	2004/12/2 7 06:38		

BRS form IS&R form Hits Details HTML

Ready

NUM

```
L21: (0) divergent with tailor$ near2 blank
```

» Flash

	U	1	Document ID	Issue Dat	Page	Title	Current
60	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6494529 B1	20021217	10	Open roof construction for a vehicle	296/222
61	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6158803 A	20001212	17	Vehicle roof with at least one cover	296/216
62	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6402215 B1	20020611	32	Vehicle cargo bed extender	296/26.
63	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6113173 A	20000905	10	Truck bed extender	296/26.
64	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5700047 A	19971223	11	Truck bed extender	296/26.
65	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5614112 A	19970325	9	Installation for positioning edge to edge	219/121
66	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5328083 A	19940712	13	Installation for the continuous butt joining	228/5.7
67	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6060682 A	20000509	11	Overlapping joint for laser welding of tailor	219/121
68	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6241307 B1	20010605	7	Tailgate structure for automotive vehicle and	296/146
69	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6776449 B2	20040817	32	Door for vehicle and its manufacturing metho	296/146
70	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6739647 B2	20040525	27	Tailored blank article and manufacturing metho	296/191
71	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6601909 B2	20030805	27	Tailored blank article and manufacturing metho	296/191
72	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6513860 B1	20030204	7	Method and apparatus for forming a three pie	296/146

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

- L1: (2) (("5614112") or ("5328083")).PN.
- L2: (23567) 228/\$.ccls.
- L3: (9) 12 and tailor\$ near2 blank
- L4: (121) 12 and weld\$ near2 blank
- L5: (9) 14 and flush
- L6: (23567) 228/\$.ccls.
- L7: (71142) 219/\$.ccls.
- L8: (0) 17 and tailor4 near2 blank
- L9: (3) 17 and tailor near2 blank
- L10: (141) 17 and weld\$ near2 blank
- L11: (8) 110 and flush
- L12: (86) 110 and step
- L13: (29) 112 and curve\$
- L14: (87) 14 and step
- L15: (17) 12 and weld\$ near2 blank with step
- L16: (8) butt near5 weld\$ with tailor\$ with blank
- L17: (41) tailor\$ with weld\$ with blank
- L18: (0) non with parallel with tailored near2 blank
- L19: (0) non with parallel with tailor\$ near2 blank
- L20: (2) parallel with tailor\$ near2 blank
- L21: (0) divergent with tailor\$ near2 blank

Failed

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (72)

UDC

Queue

Trash

Search List Browse Queue Clear

DBs USPAT Plurals


Default operator: OR Highlight all hit terms initially

divergent with tailor\$ near2 blank

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comment	Error
1	IS&R	L1	2	((("5614112") or ("5328083")).PN.	USPA T	2004/11/0 4 13:26		
2	BRS	L2	23567	228/\$.ccls.	USPA T	2004/11/0 4 13:26		
3	BRS	L3	9	12 and tailor\$ near2 blank	USPA T	2004/11/0 4 13:30		
4	BRS	L4	121	12 and weld\$ near2 blank	USPA T	2004/11/0 4 13:38		
5	BRS	L5	9	14 and flush	USPA T	2004/11/0 4 13:31		
6	BRS	L6	23567	228/\$.ccls.	USPA T	2004/11/0 4 13:32		
7	BRS	L7	71142	219/\$.ccls.	USPA T	2004/11/0 4 13:32		
8	BRS	L8	0	17 and tailor4 near2 blank	USPA T	2004/11/0 4 13:32		
9	BRS	L9	3	17 and tailor near2 blank	USPA T	2004/11/0 4 13:33		
10	BRS	L10	141	17 and weld\$ near2 blank	USPA T	2004/11/0 4 13:34		
11	BRS	L11	8	110 and flush	USPA T	2004/11/0 4 13:34		
12	BRS	L12	86	110 and step	USPA T	2004/11/0 4 13:35		
13	BRS	L13	29	112 and curve\$	USPA T	2004/11/0 4 13:35		

Ready

NUM



L2: (23567) 228/\$.ccls.  
L3: (9) 12 and tailor\$ near2 blank  
L4: (121) 12 and weld\$ near2 blank  
L5: (9) 14 and flush  
L6: (23567) 228/\$.ccls.  
L7: (71142) 219/\$.ccls.  
L8: (0) 17 and tailor4 near2 blank  
L9: (3) 17 and tailor near2 blank  
L10: (141) 17 and weld\$ near2 blank  
L11: (8) 110 and flush  
L12: (86) 110 and step  
L13: (29) 112 and curve\$  
L14: (87) 14 and step  
L15: (17) 12 and weld\$ near2 blank with step  
L16: (8) butt near5 weld\$ with tailor\$ with blank  
L17: (41) tailor\$ with weld\$ with blank  
L18: (0) non with parallel with tailored near2 blan  
L19: (0) non with parallel with tailor\$ near2 blank  
L20: (2) parallel with tailor\$ near2 blank  
L21: (0) divergent with tailor\$ near2 blank  
L22: (104) TWB  
L23: (0) L22 WITH EDGE  
L24: (23) L22 AND CURVES\$

Failed

Search List Browse Queue Clear

DBs USPAT Plurals

Default operator: OR

☒ Highlight all hit terms initially

L22 AND CURVES

Drafts  
Pending  
Active  
Failed  
Saved  
Favorites  
Tagged (72)  
UDC  
Queue  
Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
10	BRS	L10	141	17 and weld\$ near2 blank	USPA T	2004/11/0 4 13:34		
11	BRS	L11	8	110 and flush	USPA T	2004/11/0 4 13:34		
12	BRS	L12	86	110 and step	USPA T	2004/11/0 4 13:35		
13	BRS	L13	29	112 and curve\$	USPA T	2004/11/0 4 13:35		
14	BRS	L14	87	14 and step	USPA T	2004/11/0 4 13:38		
15	BRS	L15	17	12 and weld\$ near2 blank with step	USPA T	2004/11/0 4 13:39		
16	BRS	L16	8	butt near5 weld\$ with tailor\$ with blank	USPA T	2004/11/0 4 13:42		
17	BRS	L17	41	tailor\$ with weld\$ with blank	USPA T	2004/11/0 4 13:47		
18	BRS	L18	0	non with parallel with tailored near2 b	USPA T	2004/11/0 4 13:47		
19	BRS	L19	0	non with parallel with tailor\$ near2 bl	USPA T	2004/11/0 4 13:48		
20	BRS	L20	2	parallel with tailor\$ near2 blank	USPA T	2004/11/0 4 13:48		
21	BRS	L21	0	divergent with tailor\$ near2 blank	USPA T	2004/11/0 4 13:50		
22	BRS	L22	104	twb	USPA	2004/11/0		

Hits Details HTML

Ready

CAP NUM

**EAST - [lined duct:2]**

File View Edit Tools Window Help

Search List Browse Queue Clear

DBs DERWENT

Default operator: OR

☐ Plurals

☒ Highlight all hit terms initially

112 and side with flush

**Drafts**

- IS&R:
- BRS: 17 and side with f

**Pending**

**Active**

- L1: (0) ("tailor\$near2w
- L2: (0) ("tailor\$withwe
- L3: (12) tailor near2 w
- L4: (16) tailor near2 w
- L5: (64) tailor\$ near2
- L6: (1) engineer\$ near2
- L7: (229) tailor\$ near2
- L8: (13) 17 and surface
- L9: (8) 17 and side wit
- L10: (34) tailor\$ near2
- L11: (1) engineer\$ near
- L12: (107) tailor\$ near
- L13: (0) 112 and surfac
- L14: (0) 112 and side w

**Failed**

- "138"/\$.ccls. and line\$
- (296/107.19-107.20).CCL
- (296/136.01-136.13).CCL

**Saved**

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

**Drafts**

- Pending
- Active**
- Failed
- "138"/\$.ccls. and line\$
- (296/107.19-107.20).CCL
- (296/136.01-136.13).CCL

**Saved**

- Favorites
- Tagged (3)
- UDC
- Queue
- Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
3	BRS	L3	12	tailor near2 weld\$ near2 blank\$	USPA T	2004/12/2 7 05:57		
4	BRS	L4	16	tailor near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:01		
5	BRS	L5	64	tailor\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:11		
6	BRS	L6	1	engineer\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:14		
7	BRS	L7	229	tailor\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:15		
8	BRS	L8	13	17 and surface with align\$	US-P GPUB	2004/12/2 7 06:09		
9	BRS	L9	8	17 and side with flush	US-P GPUB	2004/12/2 7 06:10		
10	BRS	L10	34	tailor\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:11		
11	BRS	L11	1	engineer\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:14		
12	BRS	L12	107	tailor\$ near2 blank\$	DERW ENT	2004/12/2 7 06:15		
13	BRS	L13	0	112 and surface with align\$	DERW ENT	2004/12/2 7 06:16		
14	BRS	L14	0	112 and side with flush	DERW ENT	2004/12/2 7 06:16		

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Drafts

- IS&R:
  - BRS: 17 and side with f
- Pending
- Active
  - L1: (0) ("tailor\$near2w
  - L2: (0) ("tailor\$withwe
  - L3: (12) tailor near2 w
  - L4: (16) tailor near2 w
  - L5: (64) tailor\$ near2
  - L6: (1) engineer\$ near2
  - L7: (229) tailor\$ near2
  - L8: (13) 17 and surface
  - L9: (8) 17 and side wit
  - L10: (34) tailor\$ near2
  - L11: (1) engineer\$ near
  - L12: (107) tailor\$ near
  - L13: (0) 112 and surfac
  - L14: (0) 112 and side w
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCL
  - (296/136.01-136.13).CCL
- Saved

Search List Browse Queue Clear

DBs DERWENT

Default operator: OR

Plurals

Highlight all hit terms initially

112 and side with flush

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

- Pending
- Active
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCL
  - (296/136.01-136.13).CCL
- Saved
- Favorites
- Tagged (3)
- UDC
- Queue
- Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	0	("tailor\$near2weld\$ne ar2blank").PN.	US-P GPUB	2004/12/2 7 05:57		
2	IS&R	L2	0	("tailor\$withweld\$wit hblank\$").PN.	US-P GPUB	2004/12/2 7 05:56		
3	BRS	L3	12	tailor near2 weld\$ near2 blank\$	USPA T	2004/12/2 7 05:57		
4	BRS	L4	16	tailor near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:01		
5	BRS	L5	64	tailor\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:11		
6	BRS	L6	1	engineer\$ near2 weld\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:14		
7	BRS	L7	229	tailor\$ near2 blank\$	US-P GPUB	2004/12/2 7 06:15		
8	BRS	L8	13	17 and surface with align\$	US-P GPUB	2004/12/2 7 06:09		
9	BRS	L9	8	17 and side with flush	US-P GPUB	2004/12/2 7 06:10		
10	BRS	L10	34	tailor\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:11		
11	BRS	L11	1	engineer\$ near2 weld\$ near2 blank\$	DERW ENT	2004/12/2 7 06:14		
12	BRS	L12	107	tailor\$ near2 blank\$	DERW ENT	2004/12/2 7 06:15		
13	BRS	L13	0	112 and surface with	DERW	2004/12/2		

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Search List Browse Queue Clear

DBs DERWENT

Default operator: OR

Plurals

Highlight all hit terms initially

112 and side with flush

Drafts

- IS&R:
- BRS: 17 and side with f
- Pending
- Active
  - L1: (0) ("tailor\$near2w
  - L2: (0) ("tailor\$withwe
  - L3: (12) tailor near2 w
  - L4: (16) tailor near2 w
  - L5: (64) tailor\$ near2 v
  - L6: (1) engineer\$ near2
  - L7: (229) tailor\$ near2
  - L8: (13) 17 and surface
  - L9: (8) 17 and side wit
  - L10: (34) tailor\$ near2
  - L11: (1) engineer\$ near
  - L12: (107) tailor\$ near
  - L13: (0) 112 and surfac
  - L14: (0) 112 and side w
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCLS.
  - (296/136.01-136.13).CCL
- Saved

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

- Pending
- Active
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCLS
  - (296/136.01-136.13).CCLS
- Saved
- Favorites
- Tagged (3)
- UDC
- Queue
- Trash

	U	1	Document ID	Issue Dat	Page	Title	Current 0
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1149719 A	20011031	7	Vehicle door structure has thin gage sheet mat	
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6060682 A	20000509	11	Overlapping joint for laser welding of tailor	219/121.6
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6261701 B1	20010717	21	Laser welding system	428/577

BRS form IS&R form Hits Details HTML

Ready

NUM



EAST - [lined duct:2]

File View Edit Tools Window Help

Drafts  
IS&R:  
Pending  
Active  
L1: (1) engineered near2 welded near2  
L2: (110) tailored near2 blank  
Failed  
"138"/\$.ccls. and line\$  
(296/107.19-107.20).CCLS.  
(296/136.01-136.13).CCLS.  
Saved  
S1: (5) (("5545361") or ("5799991"))  
S2: (7) (("5092512") or ("5124186"))  
S3: (6) (("4165113") or ("4221413"))  
S4: (5) (("5,092,512") or ("6,406,0  
S5: (1148) ((293/15) or (293/102) o  
S6: (5) (("4,615,411") or ("4,347,2  
S7: (4) (("4592886") or ("6592069")  
S8: (1) ("3934064").PN.  
S9: (1) ("20008201").PN.  
S10: (1) ("2789043").PN.  
S11: (1) ("4615411").PN.  
S12: (3) (("10005718") or ("2991647  
S13: (6) (plastic near2 metal with

Search List Browse Queue Clear

DBs US-PGPUB;USPAT

Default operator: OR

Plurals Highlight all hit terms initially

tailored near2 blank

Structured form Custom form BRS form IS&R form Hits Details Image

Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error D
1	BRS	L1	1	engineered near2 welded near2 blank	US-P GPUB	2004/12/2 3 13:27	
2	BRS	L2	110	tailored near2 blank	US-P GPUB	2004/12/2 3 13:27	

Drafts  
Pending  
Active  
Failed  
"138"/\$.ccls. and line\$  
(296/107.19-107.20).CCLS  
(296/136.01-136.13).CCLS  
Saved  
Favorites  
Tagged (4)  
UDC  
Queue  
Trash

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Active

- L1: (0) ("tailor\$near2w
- L2: (0) ("tailor\$withwe
- L3: (12) tailor near2 w
- L4: (16) tailor near2 w
- L5: (64) tailor\$ near2
- L6: (1) engineer\$ near2
- L7: (229) tailor\$ near2
- L8: (13) 17 and surface
- L9: (8) 17 and side wit
- L10: (34) tailor\$ near2
- L11: (1) engineer\$ near
- L12: (107) tailor\$ near
- L13: (0) 112 and surfac
- L14: (0) 112 and side w
- L15: (339) (296/191).CC
- L16: (177) (296/146.5).
- L17: (662) (296/29).CCL
- L18: (0) ("117andblank"
- L19: (19) 117 and blank
- L20: (6) 117 and tailor
- L21: (0) 117 and engine
- L22: (0) 117 and engine
- L23: (11) 117 and engin

Search List Browse Queue Clear

DBs US-PGPUB:USPAT

Default operator: OR

Plurals

Highlight all hit terms initially

117 and engineer\$

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

- Pending
- Active
- Failed
  - "138"/\$.ccls. and line\$
  - (296/107.19-107.20).CCLS
  - (296/136.01-136.13).CCLS
- Saved
- Favorites
- Tagged (5)
- UDC
- Queue
- Trash

	U	1	Document ID	Issue Dat	Page	Title	Current 0
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 1149719 A	20011031	7	Vehicle door structure has thin gage sheet mat	
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1788151 A	19310106	3	Method of constructing and straightening vehic	72/379.2
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6060682 A	20000509	11	Overlapping joint for laser welding of tailor	219/121.6
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6261701 B1	20010717	21	Laser welding system	428/577
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6739647 B2	20040525	27	Tailored blank article and manufacturing metho	296/191

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Active

- L1: (0) ("tailor\$near2w
- L2: (0) ("tailor\$withwe
- L3: (12) tailor near2 w
- L4: (16) tailor near2 w
- L5: (64) tailor\$ near2
- L6: (1) engineer\$ near2
- L7: (229) tailor\$ near2
- L8: (13) 17 and surface
- L9: (8) 17 and side wit
- L10: (34) tailor\$ near2
- L11: (1) engineer\$ near
- L12: (107) tailor\$ near
- L13: (0) 112 and surfac
- L14: (0) 112 and side w
- L15: (339) (296/191).CC
- L16: (177) (296/146.5).
- L17: (662) (296/29).CCL
- L18: (0) ("117andblank"
- L19: (19) 117 and blank
- L20: (6) 117 and tailor
- L21: (0) 117 and engine
- L22: (0) 117 and engine
- L23: (11) 117 and engin

Search List Browse Queue Clear

DBs US-PGPUB:USPAT

Default operator: OR

Plurals

Highlight all hit terms initially

117 and engineer\$

Structured form Custom form BRS form IS&R form Hits Details Image Text HTML

Drafts

- Pending
- Active
- Failed
- Saved
- Favorites
- Tagged (5)
- UDC
- Queue
- Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
12	BRS	L12	107	tailor\$ near2 blank\$	DERW ENT	2004/12/2 7 06:15		
13	BRS	L13	0	112 and surface with align\$	DERW ENT	2004/12/2 7 06:16		
14	BRS	L14	0	112 and side with flush	DERW ENT	2004/12/2 7 06:16		
15	IS&R	L15	339	(296/191).CCLS.	US-P GPUB	2004/12/2 7 06:33		
16	IS&R	L16	177	(296/146.5).CCLS.	US-P GPUB	2004/12/2 7 06:17		
17	IS&R	L17	662	(296/29).CCLS.	US-P GPUB	2004/12/2 7 06:33		
18	IS&R	L18	0	("117andblank").PN.	US-P GPUB	2004/12/2 7 06:33		
19	BRS	L19	19	117 and blank	US-P GPUB	2004/12/2 7 06:35		
20	BRS	L20	6	117 and tailor\$	US-P GPUB	2004/12/2 7 06:35		
21	BRS	L21	0	117 and engineered with welded	US-P GPUB	2004/12/2 7 06:35		
22	BRS	L22	0	117 and engineered	US-P GPUB	2004/12/2 7 06:35		
23	BRS	L23	11	117 and engineer\$	US-P GPUB	2004/12/2 7 06:35		

BRS form IS&R form Hits Details HTML

Ready

NUM

EAST - [lined duct:2]

FileViewEditToolsWindowHelp

Pending

Active

L1: (2) (("5614112") or ("5328083")).PN.

L2: (23567) 228/\$.ccls.

L3: (9) 12 and tailor\$ near2 blank

L4: (121) 12 and weld\$ near2 blank

L5: (9) 14 and flush

L6: (23567) 228/\$.ccls.

L7: (71142) 219/\$.ccls.

L8: (0) 17 and tailor4 near2 blank

L9: (3) 17 and tailor near2 blank

L10: (141) 17 and weld\$ near2 blank

L11: (8) 110 and flush

L12: (86) 110 and step

L13: (29) 112 and curve\$

L14: (87) 14 and step

L15: (17) 12 and weld\$ near2 blank with step

L16: (8) butt near5 weld\$ with tailor\$ with blank

L17: (41) tailor\$ with weld\$ with blank

L18: (0) non with parallel with tailored near2 blank

L19: (0) non with parallel with tailor\$ near2 blank

L20: (2) parallel with tailor\$ near2 blank

L21: (0) divergent with tailor\$ near2 blank

Failed

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (72)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
10	BRS	L10	141	17 and weld\$ near2 blank	USPA T	2004/11/0 4 13:34		
11	BRS	L11	8	110 and flush	USPA T	2004/11/0 4 13:34		
12	BRS	L12	86	110 and step	USPA T	2004/11/0 4 13:35		
13	BRS	L13	29	112 and curve\$	USPA T	2004/11/0 4 13:35		
14	BRS	L14	87	14 and step	USPA T	2004/11/0 4 13:38		
15	BRS	L15	17	12 and weld\$ near2 blank with step	USPA T	2004/11/0 4 13:39		
16	BRS	L16	8	butt near5 weld\$ with tailor\$ with blank	USPA T	2004/11/0 4 13:42		
17	BRS	L17	41	tailor\$ with weld\$ with blank	USPA T	2004/11/0 4 13:47		
18	BRS	L18	0	non with parallel with tailored near2 b	USPA T	2004/11/0 4 13:47		
19	BRS	L19	0	non with parallel with tailor\$ near2 bl	USPA T	2004/11/0 4 13:48		
20	BRS	L20	2	parallel with tailor\$ near2 blank	USPA T	2004/11/0 4 13:48		
21	BRS	L21	0	divergent with tailor\$ near2 blank	USPA T	2004/11/0 4 13:49		

Search

List

Browse

Queue

Clear

DBs

USPAT

Plurals

Default operator: 

OR

Highlight all hit terms initially

divergent with tailor\$ near2 blank

6 S...

C...

B...

IS...

H...

De...

Im...

T...

H...

Hits

Details

HTML

Ready

NUM